

VEHICLE INSPECTION REPORT

Check-out



LEFT FRONT WING

Damage : Size : 25 cm

- scratch
- dent
- other



FRONT RIGHT WING

Damage : Size : 10 cm

- scratch
- dent
- other



REAR LEFT WING

Damage : Size : >25 cm

- scratch
- dent
- other



REAR RIGHT WING

Damage : Size : 5 cm

- scratch
- dent
- other